

SERVICE BULLETIN

 STANDARD **ALERT****KI35-SB-001/19****Ausgabe: 2**
Issue:**Datum: 18 November 2019**
Date:**1. BETROFFENE FLUGZEUGE:**

Klemm 35D mit Triebwerk Hirth HM 504 A-2, alle Werknummern

2. HINWEISE:

Die Ausgabe 1 dieses Service Bulletins wird hiermit für ungültig erklärt!

Zusammen mit dem LBA wird eine technische Lösung für alle Luftfahrzeuge mit Hirth HM 504 A-2 erarbeitet.

Der technische Inhalt dieses Dokumentes ist aufgrund der LBA Entwicklungsbetriebsanerkennung Nr. LBA.21J.0100 zugelassen.

Erstellt & Kontakt / Prepared & Contact:



Dr. Alexander Allen
Stellvertretender Entwicklungsbetriebsleiter / Authorised Representative HDO
Airbus Defence and Space GmbH
Tel: +49 (8459) 81-78834
E-Mail: alexander.a.allen@airbus.com

1. AFFECTED AIRCRAFT:

Klemm 35D with engine Hirth HM 504 A-2, all Serial Numbers

2. REMARKS:

Issue 1 of this Service Bulletin is hereby declared as invalid!

A technical solution will be developed covering all aircraft with Hirth HM 504 A-2 together with the LBA.

The technical content of this document is approved under the authority of LBA Design Organization Approval No. LBA.21J.0100.

Genehmigt / Approved:



Alexander Jenovelis
Zivile Musterprüfleitstelle / Civil Office of Airworthiness
Airbus Defence and Space GmbH

KI35-SB-001/19Ausgabe / Issue: 2
Datum / Date: 18 November 2019

Seite / Page: 1 von/of 1