

SERVICE BULLETIN

STANDARD

ALERT

BO208-SB-001/2023

Ausgabe: 1
Issue:

Datum: 16 November 2023
Date:

Diese Modifikation basiert auf folgender Änderungsnummer:

Bo208-006-2023

1. BETROFFENE FLUGZEUGE:
Bo208, (EASA.A.358) alle Werknummern

2. DRINGLICHKEIT:
Keine

3. GEGENSTAND:
Ersatz von Schlauchleitungen

4. ANLASS:
Fehlende ICA für Schlauchleitungen

5. MASSE UND SCHWERPUNKT:
Vernachlässigbar

6. ERFORDERLICHES MATERIAL:
TSO/ETSO Schlauchmaterial

7. HINWEISE:
Alle Schlauchleitungen für Treibstoff, Öl und Luft sind gemäß AC 43.13 Instand zu halten. Hierzu können nach entsprechender Inspektion gemäß AC 43.13 die Fittings wiederverwendet werden.

This Modification is covered by the following Change Approval Number:

Bo208-006-2023

1. AFFECTED AIRCRAFT:
Bo208, (EASA.A.358) all Serial Numbers

2. TIME OF COMPLIANCE:
None

3. SUBJECT:
Replacement of hoses

4. REASON:
Missing ICA for hoses

5. WEIGHT AND BALANCE:
Negligible

6. REQUIRED MATERIAL:
TSO/ETSO hose material

7. REMARKS:
All hoses for fuel, oil and air are to be maintained in accordance with AC 43.13. The fittings can be reused after appropriate inspection in accordance with AC 43.13.

BO208-SB-001/2023

Ausgabe / Issue: 1
Datum / Date: 16 November 2023

Seite / Page: 1 von/of 2

Der technische Inhalt dieses Dokumentes ist aufgrund der EASA Entwicklungsbetriebsanerkennung Nr. EASA.21J.026 zugelassen.

Erstellt & Kontakt / Prepared & Contact:



Dr. Alexander Allen
Stellvertretender Entwicklungsbetriebsleiter / Authorised Representative HDO
Airbus Defence and Space GmbH
Tel: +49 (8459) 81-78834
E-Mail: Lightweight-Aircraft@airbus.com

The technical content of this document is approved under the authority of EASA Design Organization Approval No. EASA.21J.026.

Genehmigt / Approved:



Claudia Engler
Zivile Musterprüfleitstelle / Civil Office of Airworthiness
Airbus Defence and Space GmbH
Tel: +49 (8459) 81-81266